

# Release notes



Software overview	1
Map changes	2
Map bugfixes	3
Software changes	4
Software bugfixes	5

# 1. Regular update – Changes summary



Platform	System Identification	SOP/ Previous Version (Map data 2015 Q4)	Enhancements (Map data 2017 Q1)
GEN 1.x	Was do not to 10 (1004-1000).  Based with a first of the state of experience of the state of the	<ul> <li>ECO route on Map present</li> <li>45 Countries supported</li> <li>No Apple CarPlay / Android Auto support</li> <li>No Tomtom Services support</li> </ul>	<ul> <li>ECO route removed from the map</li> <li>45 Countries supported (incl. 6 changes)</li> <li>No Apple CarPlay / Android Auto support</li> <li>No TomTom Services support</li> </ul>
GEN 2.0	Device information  Device (1977)  D	<ul> <li>45 Countries supported</li> <li>No Apple CarPlay / Android Auto support</li> <li>TomTom Services supported</li> </ul>	<ul> <li>45 Countries supported</li> <li>No Apple CarPlay / Android Auto support</li> <li>TomTom Services supported</li> </ul>
GEN 4.0	Of Express Will.  Sold with.	<ul> <li>45 Countries supported</li> <li>Apple CarPlay / Android Auto support (VF)</li> <li>No TomTom Services support</li> </ul>	<ul> <li>45 Countries supported</li> <li>Apple CarPlay / Android Auto support (VF)</li> <li>No Tomtom Services support</li> </ul>
GEN 5.0	Displace and Company Comp	<ul> <li>46 Countries supported (New: Malta)</li> <li>Apple CarPlay / Android Auto support (All cars)</li> <li>Tomtom Services supported</li> </ul>	<ul> <li>47 Countries supported (New: Cyprus)</li> <li>Apple CarPlay / Android Auto support</li> <li>TomTom Services supported</li> </ul>

# 2. Map database changes



Coverage attribute	2018 Map update	Improvement vs. 2017
Road Geometry (km)	2.177.261	+ 393.960
Street Names (count)	3.718.016	+ 558.231
Addressing (count)	137.660.393	+ 8.834.648
Highways (count)	36.134	+ 6.804
One Way Streets (count)	431.484	+ 76.969
Roundabouts (count)	111.964	+ 17.957
Speed Limits (count)	1.896.048	+ 620.372
Turn restrictions (count)	614.678	+ 298.143
Sign Information (count)	275.067	+ 71.051
Points of Interest (count)	9.727.933	+ 850.504

# 3. Software overview



Platform	Vehicle	Software version	Map database ver.	New features
GEN 1.x	TF, UB, JD, XM FL, RP, TF FL, SL FL, YN, ED, SL, XM	SW 7.8.3	117E7AC	ECO Data removed
GEN 2.0	UM, YN, UB, GB, TA, JD, JD S/P, JF, QLe, UM17MY	xx.EU.SOP.20.178	EUR.10.48.54.001.001(D.D2)	➤ TomTom Live Services
GEN 4.0	PS, TF FL, TF FL HEV, PSEV, UM, PSEV17MY ('16.7), UM17MY ('16.10)	ST.xx.EUR.E530.170925	EUR.09.41.43.712	Only for UM, PS, VF:  > Android Auto > Apple CarPlay
iAVN	PS, JF_PHEV, JF Wagon, JF_ PHEV_WGN, JA, YB, RP, DE_ HEV, JF_17MY, JD_17MY, QL_17MY, JD_17MY_WGN	XXX.EUR.SOP.005.170927	EUR.09.47.50.582.002.2(D.C1): Normal / HEV Europe  EUR.09.47.50.582.002.2(D.C1/E.C1): EV / PHEV Europe	<ul><li>TomTom Live Services</li><li>Android Auto</li><li>Apple CarPlay</li></ul>

# 4. Map changes - GEN1.x



#### **Map version:** 117E7AC > Gen1.x

Mayor changes	Details
Change source data	<ul> <li>HERE Map DB: 15Q4 → 17Q1</li> <li>HERE Traffic Pattern: 15Q4 → 16Q4</li> <li>HERE HYUNDAI/KIA POI: November 2016</li> <li>ZENRIN Junction View: 15Q4 → 17Q1</li> </ul>
Coutries covered	> 45 Countries
Reflect the cost of Route – Planning data	Reflect the cost of Route-Planning which is tuned for unpaved road of Northern Europe including Iceland
Fixed the house-number for POIs	Fixed using matching table because the actual house-number for POIs was not applied to latest map version
Modify the multilingual name of gas station for POI	➤ Changed the name of the gas station in Swedish: Bensinstation → Bränslestation

### 4.1 Map changes – GEN2.0



**Map version:** EUR.10.41.54.001.001 > Gen 2.0

Mayor changes	Details
Change source data	<ul> <li>HERE Map DB: 15Q4 → 17Q1</li> <li>HERE Traffic Pattern: 15Q4 → 16Q4</li> <li>HERE HYUNDAI/KIA POI: November 2016</li> <li>HERE Hydrogen Station POI: 15Q4 → 17Q1</li> <li>ZENRIN Junction View: 15Q4 → 17Q1</li> </ul>
Coutries covered	> 45 Countries
Apply to latest border crossing data	> Apply to the data from HMETC
Modify the Near-by search data	➤ Modify the Near-by search data, because POIs of Travel Category can not search at all
Reflect the cost of Route – Planning data	<ul> <li>Reflect the cost of Route-Planning which is tuned for unpaved road of Northern Europe</li> <li>including Iceland</li> </ul>
Modify the multilingual nam e of gas station for POI	➤ Changed the name of the gas station in Swedish: Bensinstation → Bränslestation

# 5. Map bugfixes – Gen 4.0



	Map version: EUR.09.41.43.712(17 Q1) > Gen 4.x			
	> 45 Countries covered	Keep left but need "turn right" at right side curved point > fixed	> Improved elevation contour quality > fixed	Applied guidance by checking NOTHRU PROHIBIT
	Improved to load several missed or mismatched transliteration language street name of POI > fixed	➤ No guidance but need "keep on the left lane and turn left"> fixed	<ul><li>Made Cyprus as non-target country</li><li>fixed</li></ul>	Fixed error texts are displayed on 10km scale
	<ul><li>Fixed error unnecessary polygon</li><li>fixed</li></ul>	<ul><li>Change service area route guidance</li><li>fixed</li></ul>	Changed wrong sharply right turn RG to left turn > fixed	> Fixed error duplication house number
Changes	Improved route guidance load missing RG at IC > fixed	Fixed not loaded complex polygons on 7 level > fixed	> Delete city text in ocean	> Improved admin texts
გ	Fixed background of island oLevel world map.> fixed	> Added far east Russia territory > fixed	Display Madrid text on 1000KM scale	➤ Improved RG not to guide STF → STF link at round about
	Improved not to load unnecessary country border > fixed	Delete PJ-C forward direction when exist PJ-M and PJ-C by spec > fixed	Deleted RG in an abrupt turn road of mountain area > fixed	Improved RG to not to load duplicate guidance at the IC and PJ-M link
	<ul><li>Improved not to overlapped flag</li><li>fixed</li></ul>	➤ Changed spec rest area POI > fixed	> Increased the number of road number	Ramp average speed patch to original value
	Improved not to load unnecessary land polygon> fixed	<ul> <li>Polyline to improve display highways on upper level</li> </ul>	> Improved river not to disconnected	<ul> <li>Added search data for common postal code of unnamed road</li> </ul>



		Map version: EUR.og.4	7.50.581(17 Q2) > iAVN	
	46 Countries covered	Improved not to display road sign symbol> fixed	If several official names exist for one city name, improved to display the its own country's language name firstly	Polyline to improve display highways on upper level
	Deleted internal border of UK between England, Scotland, Wales and Northern Ireland > fixed	Added Russian language in Belarus for search	> Fixed error unnecessary polygon	Fixed Mismatching NRT symbol
Changes	<ul><li>Deleted lane connectivity information</li><li>&gt; fixed</li></ul>	Lower level to prevent city ENG or RUS mode text is present on the ocean and loaded only on lands or islands	Improved route guidance load missing RG at IC	Improved not to load unnecessary land polygon
	Improved RG point at IC with special explication point > fixed	Improved possible to search street name after premium postal code filter in Netherlands and UK	Fixed background of island oLevel world map	Improved city names are listed in twice by merging admin code (ie: Stockholm in Sweden, Turku in Finland, etc.)
	<ul><li>Improved to add turn RG at the intersection by specifying the spec.</li><li>&gt; fixed</li></ul>	Improved to load several missed or mismatched transliteration language street name of POI	> Improved not to overlapped flag	

# 6. Software Changes



Platform: SW 7.8.3> Gen 1.x	Content
	➤ The Icelandic letter "Þ" modified from "P" to "T"
Change	Route planning algorithm improved for Northern Europe and Iceland
Change	➤ Latest house-numbers for POIs updated
	Swedish word for gas station updated: Bensinstation à Bränslestation

# 7. Software Bugfixes



Platform: SW xx.EU.SOP 178> Gen 2.0	Content
	> [Edit] option added for SWRC mode
	An option added to turn On/Off the OSD display when changing songs from Media
	➤ [Help] added in the settings
	Pressing the phone key on the SWRC to run the BT pairing procedure directly when there is no paired phone
ci.	Repeat and shuffle button separated in Media
Change points	Russian language updated to display USB media tag information
	➤ Hyundai Service POIs updated
	EU Maps - Road signs updated
	Anti-hacking system updated
	> BT hands-free performance improved for DM and QL
	Reverse warning priority added

# 7.1 Software Bugfixes



Platform: ST.xx.EUR.E530.170925 > Gen 4.x	Content
	> Apple Car play and Android auto introduction into <b>UM, PS carlines</b>
	System SW size reduced to ~ 7GB
	<ul> <li>Track list not updated in MY Music after entering the MY Music</li> <li>Removal of 3rd Party app features</li> </ul>
Change	<ul> <li>When CP call active, system does not show OSD message for Seek Up / Down</li> <li>When Home Screen Displayed no OSD message to be displayed</li> <li>OSD layout has no Eclipsis Property</li> <li>Incoming call OSD cleared when in Rear Gear</li> <li>Car Performance improved during high System load</li> <li>Removal of 3rd Party app features</li> <li>When Map HK is pressed, OSD does not clear</li> </ul>

# 7.2 Software Bugfixes



Platform: SW SOP.005.3.170927 > iAVN	Content
	> BT hands-free performance improved for QL
	RDS display and station list display algorithm in Radio improved
	> Delay occurs when switching to radio screen
	Reverse warning priority added
	> Added the Regional function in radio
	➤ Green car, fuel efficiency display changed to 3-digit
	➤ EU dealer mode added
Change points	➤ Low battery display spec changed
	<ul> <li>DE PHEV: 25% or less, low battery color displayed</li> <li>Others: less than 25%, low battery color displayed</li> </ul>
	Mute icon for CarPlay added on the status bar
	► [iAVN] HeadLamp warning PU deleted.
	➤ [iAVN] EU CK external amp model, ASD (Active Sound Design) feature added
	➤ [iAVN] Help button in Drive mode settings removed
	➤ [iAVN] Rear camera driving view added