

2018 MapCare Manual for Dealers

Version 1.4











This document is split into four sections:









1.Downloading the map updates

Compatibility table	1.1
Regular update – Changes summary	1.2
Map database changes	1.3
Downloading the updates	1.4

1.1 Compatibility table

GEN 1.x	Venga (YN) Cee'd (ED JD)	Sorento (XM, XMFL) Optima (TF, TFFL)	Rio (UB) Carens(RP)
	sportage (SL, SLFL)		
GEN 2.0	Picanto (TA) Rio (UB)	Venga (YN) Optima (JF)	New Sportage (QL) New Sorento (UM)
GEN 4.0	Soul (PS, PSEV) Sorento (UM) Optima (TF, TF HEV)		
iAVN	Niro (DE HEV, DE PHEV) Sportage 2017 (Qle) Soul 2017 (PS PE)	Carens (RP PE) Rio (YB), Stonic (YB CUV) Stinger (CK)	Sorento PE (UM PE) Cee'd (JD MY17) Optima (JF 2017, JF PHEV, JF WGN, JF WGN PHEV)
DAUDIO	Rio (YB) Stonic (YB CUV)		



Downloading and creating a SD card with the All Software package is the fastest and most convenient way to create the 2018 update kit

Step 1

Download "All Software"* (see **1.2.8**)

Step 2

Prepare the SD card (see **2.6 - 2.6.2**)

Step 3

Download map data* files as needed (see **1.2.4 – 1.2.9**)

Step 4

Continue with 2.7

* Gen 1.x map data is included in "All Software" file









Software needed for download:

- Windows 7, Windows 8 or Windows 10
- Web browser like FireFox, Chrome or Internet Explorer
- WinZIP or 7Zip extraction tool

Hard drive space:

(

- Map data files need to be stored on PC for copying to Vehicle SD card (approx 42 GB)
- System Software will be copied one time to separate SD card or USB stick and can be deleted from hard drive after copy process

Platform	Component	File size after extraction
GEN 1.x (5.1.3)	Map Data and Software	3.15 GB
GEN 1.x 2018 Update	Map Data and Software	5.08 GB
GEN 2.0 2018	Map Data	7.40 GB
Update	System Software	2.80 GB
GEN 4.0 2018	Map Data	11.60 GB
Update	System Software	4.73 GB
iAVN 2018	Map Data	17.00 GB
Update	System Software	2.62 GB
DAUDIO	System Software	0.781 GB

1.2.2 How to download the update



Please use your Username and Password to Log In

For security reasons, you will have to change to a new password after first Log In



IMPORTANT NOTICE The 2018 Map Master and Software downloads are now available. In the attached 2018 MapCare manual you will find the new moreculars for this new version.

Welcome to the HERE Dealer Order Centre The HERE Dealer Order Centre gives approved dealers access to HERE products and services.

Master kits Download a Master kit to update the map in multiple vehicles

MapCare Map and Software updates are available for Authorized Dealers at:

http://www.navigation.com/doc-emea















Gen 1.x 2018 is the latest System Software and Map update In most cases, you only need to download this package. The f	ile name is Kia_Gen1x_2018.zip
Gen 1.x 2018 SKU: E3242011827001	 I have read and accept the Export Control Terms. Download
Gen 1.x 5.1.3 is only needed if the system software is pre 5.1	

In this case, you need to download and install both packages. The file name is **Kia_Gen1x_5_1_3.zip**

Gen 1.x 5.1.3 2018	I have read and accept the Export	
	Control Terms.	
SKU: E3242011826001		Download

To request the personal download link, check the "Export and Control Terms" box and click [Download]











To request the personal download link, check the "Export and Control Terms" box and click [Download]







Gen 4.x Software is the latest System Software update
The file name is Kia_Gen4_Software_2018.zip

Gen 4.x	Software	2018
---------	----------	------

SKU: E3282011827001

I have read and accept the Export

Control Terms.

Download

To request the personal download link, check the "Export and Control Terms" box and click [Download]











iAVN Map 2018 is the latest Map update The file name is Kia_iAVN_Map_2018.zip iAVN Map 2018

SKU: E3282011826002

I have read and accept the Export
 Control Terms.

iAVN Software is the	e latest	System So	oftware	update
The file name is Kia	_iAVN_	_Software_	_2018.zij	C

iAVN Software 2018

SKU: E3282011827002

I have read and accept the Export

Control Terms.

Download

To request the personal download link, check the "Export and Control Terms" box and click [Download]









To request the personal download link, check the "Export and Control Terms" box and click [Download]

By clicking "Save File" the selected file will be downloaded to your computer

* Gen 1.x includes Map and Software



To request the personal download link, check the "Export and Control Terms" box and click [Download]

By clicking "Save File" the selected file will be downloaded to your computer

* Gen 1.x includes Map and Software



2. Creating your Service Tool Kit (STK)

Preparing your Service Tool Kit (STK)	2.1
Media carriers	2.2
Required media	2.2
Preparing USB and SD cards	2.4
Locating the 2018 Map Update files	2.5
Preparing the 2018 STK	2.6
Creating the Map Data folder	2.7
Verifying Map Data files	2.8

×

2018 system software and map updates are available as a **download** to you

As highlighted in the Download Manual, **each platform is split into:**

Software

- It needs to be copied to a media (SD Card or USB stick, depending on the navigation platform) one time only
- After copying the software to the media, you may delete the files from your computer

Map data

The 2018 files need to stay on your computer and be copied to the vehicle's SD card for every update

 $\mathbf{\cdot}$



The process is universal for all navigation platforms:

- **1.** Download the files
- **2.** Extract the files to your hard drive
- **3.** Copy the files to SD card or USB stick

2.2 Media carriers

We suggest to create **3 different media carriers**:













Platform	Media	Size	Comment
GEN 1.X 2018	USB Stick	8 GB	If you need to purchase a new USB stick, a common consumer grade version is sufficient (e.g. Intenso 8 GB USB-Stick)
GEN 1.x (5.1.3) DAUDIO	USB Stick	8 GB	If you need to purchase a new USB stick, a common consumer grade version is sufficient (e.g. Intenso 8 GB USB-Stick)
GEN 2.0 2018 Update		SD Card 32 GB	In case you would like to create one SD card per navigation platform or need to purchase more SD cards, please purchase a common consumer grade SD card (e.g. SanDisk Ultra SDHC 32GB UHS-I Class 10)
GEN 4.0 2018 Update	SD Card		This manual will explain how to create one SD card containing 2018 software versions of Gen 2.0. Gen 4.0 and iAVN platforms
iAVN 2018 Update			

℅

2.4 Preparing USB and SD cards





After downloading the files, please open the folder containing the downloads

The **file names** are:

Platform	Component	File name	
GEN 1.X 2018	Map Data and Software	Kia_Gen1x_5_1_3.zip	
GEN 1.x (5.1.3)	Map Data and Software	Kia_Gen1x_2018.zip	
CEN a a par 9 Undata	Map Data	Kia_Gen2_Map_2018.zip	
GEN 2.0 2018 Opdate	System Software	Kia_Gen2_Software_2018_2.zip	
	Map Data	Kia_Gen4_Map_2018.zip	
GEN 4.0 2016 Opdate	System Software	Kia_Gen4_Software_2018.zip	
iAV/N 2018 Undate	Map Data	Kia_iAVN_Map_2018.zip	
IAVIN 2018 Opdate	System Software	Kia_iAVN_Software_2018_2.zip	
DAUDIO 2018 Update	System Software	Kia_DAUDIO_A_2018.zip	

Ś

 \mathbf{X}

These steps need to be performed **ONE TIME** only to create the STK As soon as the STK is ready, you may delete the files from your PC

Step 2

Step 1

Please open the folder with the downloaded ZIP files and locate the Kia_Genx_all_Software_2018.zip

Kia_Genx_all_software.zip

click on the file and s

Right click on the file and select [WinZip]

	Open with WinZip	
	Print	
	Scan with System Center Endpoint Protection	
	Open with	•
9	WinZip	•
×	Scan with Mawarebytes Anti-Malware	
	Restore previous versions	
	Send to	•
	Cut	
	Сору	
	Create shortcut	
	Delete	
	Rename	
	Properties	
	riopedes	

Step 3

Select **[Extract to folder]**. WinZip will now extract the files to a new folder named like the nav platform

Ĵ	Extract to	
Ĵ	Extract to here	
Ĵ	Extract to folder	C:\2018Update\ Kia_Genx_all_Software_2018
Ĵ	Extract to folder	
<u> </u>	Extract to folder	



2.6 Preparing the 2018 STK – GenX All Software 2018

4

These steps need to be performed **ONE TIME** only to create the STK As soon as the STK is ready, you may delete the files from your PC

Step 4	Step 5	Step 6
WinZip is now extracting the files	The new folder is visible now	Double Click the folder to open it until you see the files
Extracting eu20_upgrade.lgu	Kia_Genx_All_Software	BOOTLOADER eu20_hei_upgrade.lgu CAVNEU_CK eu20_kei_upgrade.lgu CAVNEU_K eu20_kse_upgrade.lgu CAVNEU_UM eu20_kse_upgrade.lgu IBOX eu20_ksp_upgrade.lgu micom eu20_upgrade.lgu System Ige.upgrade Aberaham.exe upgrade.lgu Aerith.exe upgrade.lgu Aerith.exe upgrade.lgu checksums.md5 upgrade_B.map @ dummy.mp3

2.6.1 Preparing the 2018 STK – GenX All Software 2018

 \mathbf{X}



These steps need to be performed **ONE TIME** only to create the STK As soon as the STK is ready, you may delete the files from your PC

Step 7	Step 8	Step 9
Select the files in the folder. Right click on the marked files and select [Copy]	Please right click on the SD card folder and paste the data on the SD card	Now you created a SD card to update the following system software to 2018 version:
BOOTLOADER eu20_hei_upgrade.lgu CAVNEU_CK eu20_hse_upgrade.lgu CAVNEU_K eu20_kse_upgrade.lgu CAVNEU_UM eu20_kse_upgrade.lgu BOX eu20_kse_upgrade.lgu BOX eu20_upgrade.lgu System lge.upgrade Aberaham.exe upgrade Aberaham.exe upgrade_B.map Poperies	View Sort by Group by Refresh Customize this folder Paste Paste short ut Undo Rename Ctrl+Z	 Gen 1.x Gen 2.0 Gen 4.0 iAVN

2.6.2 Preparing the 2018 STK – GenX All Software 2018





KIA

Gen 1.x version 5.1.3 is only needed for vehicles, that do not have a 5.1.3 or higher installed. In case a vehicle has 5.1.2 or lower, you need to install 5.1.3 first and 2018 update afterwards You need to prepare a separate USB stick for this version

4/

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_Gen1.x_5.1.3.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible



Gen 1.x version 5.1.3 is only needed for vehicles, that do not have a 5.1.3 or higher installed. In case a vehicle has 5.1.2 or lower, you need to install 5.1.3 first and 2018 update afterwards You need to prepare a separate USB stick for this version

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] System upgrade.lgu checksums.md5 upgrade_v8.lgu lge.upgrade	Right click and paste the data on the USB stick	The USB stick will contain 3.15 GB

2.6.4 Preparing the 2018 STK - GEN 1.X 2018 Update (1/2)

KIN

These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_Gen1x_2018.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible

2.6.4 Preparing the 2018 STK - GEN 1.X 2018 Update (2/2)



These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] BOOTLOADER System Aberaham.exe Aberaham.exe checksums.md5 dummy.mp3	Right click and paste the data on the USB stick	The USB stick will contain <mark>5.08 GB</mark>

2.6.5 Preparing the 2018 STK - GEN 2.0 2018 Update (1/2)

KIA

These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_Gen2_Software_ 2018.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible

2.6.5 Preparing the 2018 STK - GEN 2.0 2018 Update (2/2)



These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] eu20_kse_upgrade.lgu eu20_kse_upgrade.lgu eu20_kse_upgrade.lgu	Please right click on the SD card folder and paste the data on the SD card	Now you created a SD card to update Gen 2.0 system software to 2018 version





2.6.6 Preparing the 2018 STK - GEN 4.0 2018 Update (1/2)

KIA

These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_Gen4.x_Softwar e_2018.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible

2.6.6 Preparing the 2018 STK - GEN 4.0 2018 Update (2/2)



These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] BOX BOX.md5	Please right click on the SD card folder and paste the data on the SD card	Now you created a SD card to update Gen 4.0 system software to 2018 version

2.6.7 Preparing the 2018 STK - iAVN 2018 Update (1/2)

KIA

These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_iAVN_ Software_2018.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible

2.6.7 Preparing the 2018 STK - iAVN 2018 Update (2/2)



These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

ર્

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] CAVNEU_CK CAVNEU_K CAVNEU_K CAVNEU_UM checksums.md5	Please right click on the SD card folder and paste the data on the SD card	Now you created a SD card to update iAVN system software to 2018 version

KIA

These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 1	Step 2	Step 3	Step 4
Open the folder with the downloaded ZIP files and locate the Kia_DAUDIO_A_201 8.zip	Right click on the file and select [WinZip]	Select [Extract to folder] . The files will be extracted to a new folder named like the navigation platform	After WinZip has extracted the files, the new folder will be visible

2.6.8 Preparing the 2018 STK - DAUDIO 2018 Update (2/2)



These steps need to be performed **ONE TIME** only to create the STK. As soon as the STK is ready, you may delete the files from your PC

Step 5	Step 6	Step 7	Step 8
Double click the folder to open it until you see the files	Select the files in the folder. Right click on the marked files and select [Copy] DAUDIO_A checksums.md5 cannon.mp3 	Please right click on the USB stick and paste the data on the USB.	Now you created a SD card to update DAUDIO system software to 2018 version

2.7 Creating the Map Data folder

Step 1

Create a new folder on your computer and name it "Map Update 2018"

📙 Map Update 2018
Gen 2.0
Gen 4.0
iAVN

Step 2

This folder will serve as your **central storage** of the Map Data

X

Step 3 Kia_Gen2_Map_2018 Kia_Gen4x_Map_2018 Kia_iAVN_Map_2018

Copy the downloaded and extracted Map Data files into this folder. You will need approx. **45 GB** of hard disk space



Right click on the individual map data folder and **select [Properties]** The file properties must match the below information

Gen 2.0 Map

Gen 4.0 l	M	a	р
-----------	---	---	---

iAVN Map

Туре:	File folder
Location:	C:\Users\Winter\Desktop\2017RU\Kia\Gen2.0 201
Size:	7.40 GB (7,955,382,428 bytes)
Size on disk:	7.40 GB (7,956,496,384 bytes)
Contains:	665 Files, 7 Folders

Typ:	Dateiordner
Ort:	C:\Users\Winter\Desktop\2017_RU Patch
Größe:	11,6 GB (12.560.372.475 Bytes)
Größe auf Datenträger:	11,6 GB (12.561.129.472 Bytes)
Inhalt:	364 Dateien, 66 Ordner

Typ:	Dateiordner
Ort:	C:\Users\Winter\Desktop\2017_RU Patch
Größe:	17,0 GB (18.329.918.314 Bytes)
Größe auf Datenträger:	17,0 GB (18.330.980.352 Bytes)
Inhalt:	552 Dateien, 126 Ordner



3. Updating the vehicles

	GEN 1.X	3.1
<u>e</u>	2 GEN 2.0	3.2
	GEN 4.0	3.3
	iAVN	3.4
	DAUDIO	3.5



	Venga (YN)
	Cee'd (ED JD)
	Sportage (SL, SLFL)
GEN 1.x	Sorento (XM, XMFL)
	Optima (TF, TFFL)
	Rio (UB)
	Carens (RP)





Before performing the update make sure that the vehicle is equipped **with software 5.1.3 or newer**

If not, please, refer to the relevant TSB



If the current version is lower than 5.1.3, the pop-up screen is displayed as shown below:



Upgrade the software to 5.1.3 version according to the previous TSB

In case of above screen message, please refer to TSB: KGE12-92-P140-YNEDSLXMTFUBQB



Insert the USB with the upgrade files into the car's USB port



The system will automatically recognize the new system and map software and displays current and new software and map information

Press [OK] then [Agree] to proceed

Sot	ftware	e Upgrade!	-
Bluetooth		Firmware	
Current version	3.2.2	Current version	1.7.3
New version	3.2.2	New version	1.7.3
System Software		Мар	
Current version	7.7.4	Current version	415E7AB
New version	7.8.3	New version	117E7AC
OK		Canc	el

The system will start performing the upgrade for both the system and the map



Long press on the [SETTINGS] button



Check the software and map versions



	System version	7.8.3	
GEN 1.X	Navi app version	EU.10.49.41	
	Map database version	117E7AC	



	Picanto (TA)
	Rio (UB)
CENDO	Venga (YN)
GEN 2.0	Optima (JF)
	New Sportage (QL)
	New Sorento (UM)



×





3.2.1 GEN 2.0 - Step 1 - in vehicle System Software Upgrade (Duration <12 min)

Remove the map SD Card from the SD-Card slot. Insert the SD card with the upgrade files into the SD-Card slot



System automatically detects an upgrade file on the SD Card and displays a window with old and new software information

System S/W		New Version	
System S/W	TL.EU.SOP.20 - 1.6.6	TL.EU.SOP.20 - 1.7.8	
Firmware	TL.EU.SOP - 1.0.9	TL.EU.SOP - 1.3.0	
Navi. App TL.EU.SOP - 094947 TL.EU.SOP - 104955			
Up	grade	Cancel	
Click on	the [Upgrad	<mark>e]</mark> then [Agr	

System starts the upgrade process Once the update is completed, the system automatically reboots Long press on the **[SETTINGS]** button



Check that the new S/W version is displayed Remove SD Card

REG 00:27		In some cases
Device information	U	"Invalid Map
Device ID C4366CF11FBC		Version" appears
For further information about your Map upgrade,		
please visit the website.		This is caused by
		the removal of Man
Software ver. : UM.EU.SDP.10.178		
Firmware ver.: UM,EU,SOP.10.130		SD Card and has no
Navi app ver. : UM.EU.SOP.10.49.55		impact on the
Map ver. : EUR.10.48.54.001.001(D.D2)		software update





Check that the Map SD is unlocked



Select SD card drive and click the right mouse button and click [FORMAT]



Use the following settings: File System: FAT32 (Default) Allocation Unit Size: 32KB



Click [START] button

Start format by clicking [OK] When format is done click **[OK]**



Duration: <5 sec

Select [LGENavi]

left click on [COPY]

Click right mouse button and



Open the GEN 2.0 map folder on your PC



Right click on the SD card drive and click on **[PASTE]** to copy the map on the SD Card Duration: **<20 min**



DO NOT COPY OTHER

FILES TO THE SD CARD

Check copy completion Select ALL files Click right mouse button and click [**PROPERTIES**]



Check number of data / folder and size



Put the update Map SD Card back in the SD slot. The system will reboot. Long press on the **[SETTINGS]** button



Check the Navi app and Map versions



GEN 2.0	System ver.	XX.EU.SOP.XX.178	
	Navi app ver.	XX.EU.SOP.10.49.55	
	Map database ver.	EUR.10.48.54.001.001(D.D2)	

3.3 GEN 4.0 compatibility table



	Soul (PS, PSEV)
GEN 4.0	Sorento (UM)
	Optima (TF, TF HEV)







3.3.1 GEN 4.0 - Step 1 – in vehicle System Software Upgrade (Duration <20 min)





System will reboot once the update is complete (< 20 min)



Go back to **[SYSTEM INFO]** to check if the new S/W version is displayed





Check that the Map SD is unlocked



slot of your computer

Select SD card drive and click the right mouse button and click [FORMAT]



Use the following settings: File System: FAT32 (Default) Allocation Unit Size: 32KB



Click [START] button

Start format by clicking [OK] When format is done click **[OK]**



Duration: <5 sec

Select ALL files

left click on [COPY]

Click right mouse button and



Open [MAP Update 2018] folder on your PC Open [Kia_Gen4x_Map_2018]



Right click on the SD card drive and click on **[PASTE]** to copy the map on the SD Card Duration: **<20 min**



Check copy completion Select ALL files Click right mouse button and click **[PROPERTIES]**

	D Text.Info, Properties
	General Customize Checksums
	364 Files, 66 Folders
	Type: Multiple Types
	Location: All in \\Hmeo-cloud\\hmeo\\HMEO\02_Quality_Gener
.	Size: 11.6 GB (12,560,372,475 bytes)
	Size on disk: 11.6 GB (12,561,252,352 bytes)
	Attributes
	OK Cancel Apply

DO NOT COPY OTHER FILES TO THE SD CARD

Check number of data / folder and size





Check that the new version is displayed

	System ver.	E530.170925	
	Navi app ver.	ST4.EUR.KMC.170921.XXXXXXX	
GEN 4.0	Map ver.	EUR.10.41.46.551.001(D.D2)	
		EUR.10.41.46.551.001(D.D2/E.D1)	For EV



I /		- (KIA
	Niro (DE HEV, DE PHEV)	
	Optima (JF 2017, JF PHEV, JF WGN, JF WGN PHEV)	
	Sportage 2017 (Qle)	
	Soul 2017 (PS PE)	
: 437/81	Carens (RP PE)	
IAVIN	Rio (YB)	
	Stonic (YB CUV)	
	Stinger (CK)	
	Sorento PE (UM PE)	
	Cee'd (JD MY17)	

<u> </u>

×

Remove the map SD Card from the SD-Card slot. Insert the SD card with the upgrade files into the SD-Card slot



System automatically detects an upgrade file on the SD Card and displays a window with the new software information



System starts the upgrade process During the upgrade process, the system will boot several times Wait until the window with **[Upgrade completed]** is

Click on the **[SETTINGS]/ [SETUP] button** Scroll the screen to the next page and click on the **[SYSTEM INFO]** icon

Check that the new S/W version is displayed Remove SD Card

f	:			
🕸 System info 🕤				
Version info	Software	RP.EUR.50P.005.9.180306		
Update	Firmware	RP.EUR.0.5.250.180110.MICOM		
	NAV APP	STD_AVN_MID.EUR.KMC.170927.a803344		
Default	Мар	EUR.10.41.46.701.002.2(D.D1)		
	Device ID	2299001168		

displayed

In some cases "Invalid Map Version" appears

This is caused by the removal of Map SD Card and has no impact on the software update



Check that the Map SD is unlocked



slot of your computer

Select SD card drive and click the right mouse button and click [FORMAT]



Use the following settings: File System: FAT32 (Default) Allocation Unit Size: 32KB



Click [START] button

Start format by clicking [OK] When format is done click **[OK]**



Duration: <5 sec



Open [MAP Update 2018] folder on your PC Open [Kia_iAVN_Map_2018]



Select ALL files Click right mouse button and left click on **[COPY]**



Right click on the SD card drive and click on **[PASTE]** to copy the map on the SD Card Duration: **<20 min**



DO NOT COPY OTHER FILES TO THE SD CARD Check copy completion Select ALL files Click right mouse button and click **[PROPERTIES]**



Check number of data / folder and size



Re-insert the upgraded map SD-Card into the SD-Card slot If the system is **ON**, it will reboot



Click on the [SETTINGS]/[SETUP] button Scroll the screen to the next page Click on the [SYSTEM INFO] icon **Check** that the new software, Navi app version and Map version are displayed

		ft		-:	
	🔅 System in		ıfo	É	
		Version info	Software	RP.EUR.SDP.005.9.180306	
		llodate	Firmware	RP.EUR.0.5.250.180110.MICOM	
		00000	NAV APP	STD_AVN_MID.EUR.KMC.170927.a8033	14
		Default	Мар	EUR.10.41.46.701.002.2(D.D1)	
			Device ID	2299001168	
	System ver.	XX.EUR	.SOP. 002	.9.180125	Stinger and Sorento PE
AVN		XX.EUR	.SOP. 005	.9.180306	
	Map ver.	EUR.10	.41.46.701.	.002.2(D.D2)	
		EUR.10	.41.46.701.	.002.2(D.D2/E.D1)	For PHEV



DAUDIO	Rio (YB) Stonic (YB CUV)









Please refer to TSB for detailed update instructions.



 \mathbf{A}







4.1

4.2

4. Frequently Asked Questions

HERE Contact Center FAQ



In case you experience problems or the email does not reach you, please contact the HERE Contact Center directly:

Local toll free number Germany Local toll free number France Local toll free number Italy Local toll free number UK

All others countries:

International toll free number International not toll free number 0800 181 6065 0800 914 478 800 781 145 08081 013885

00800 18 23 53 22 +31 555 384 245 Please, contact your Distributor, Sales Organization or HERE before submitting a field claim



?

lssue	Solution
The update of system software fails or map data fails	 You might have not formatted the SD card / USB properly. Please, refer to slides 18, 19 and 20. Also, please note that GEN 2.0, GEN 4.0 and iAVN systems only recognize SD cards with max 32GB (slide 19) You might have not copied the files correctly. Please, refer to slides from 21 to 30 To check the general update process per platform, please, refer to section 3
Download speed is slow	 Your internet connection might be too slow. Please, try to download single files only instead of all files at once. You can also schedule downloads for hours of low frequency of your business (e.g. over night) To check estimated download size per platform, please, refer to slide 8
The SD card is not recognized by the system	 You might have not formatted the SD card / USB properly. Please, refer to slides 18, 19 and 20. Also, please note that GEN 2.0, GEN 4.0, pGEN 2.0 and GEN 5.0 systems only recognize SD cards with max 32GB (slide 19) You might have not copied the files correctly. Please, refer to slides from 21 to 30 To check a detailed overview of file size, please refer to slides 8 and 19 To check a detailed overview of files names per platform, please refer to slides 11 to 15 and slide 21





